



# LAUNDRY INSTRUCTIONS

## COTTON/POLY BLENDED NAPERY

Load the washer according to manufacturer's specifications. Underloading or overloading can result in poor stain removal or in setting wrinkles.

Use the cycle recommended for your cotton/polyester napery. The first step should be a warm flush to avoid setting greasy stains. This should be followed by a hot wash (150-160°). Rinses should be progressively lower temperatures.

	Water Level	Temperature °F	P.H.
BREAK	LOW	100-110	
SUD	SLOW	150-160	10.5-11
DRAIN			
RINSE	HIGH	110-120	
DRAIN			
RINSE	HIGH	110-120	
DRAIN			
SOUR	LOW	100-110	5.5-7

If stains remain after one wash, add one cup of liquid chlorine bleach diluted with 20 gallons of water during laundering. Add bleach before putting napkins or tablecloths in washer only to remove stubborn stains.

BLEACH	LOW	140-145	10.2-10.8
--------	-----	---------	-----------

Load the dryer to only 1/3 to 1/2 of the rated capacity. This will allow the tumbling necessary to eliminate wrinkles coming from the washer. Drying temperatures should be at least 30° hotter than washing temperatures. Cool down cycle should be maintained at 100°F.

Remove and fold tablecloths immediately after completion of cooling cycle.

To prevent Alkaline hydrolysis of the polyester, do not exceed P.H. value of 11.0.

Do not use softeners and bacteriostats that contain ammonium compounds.

**IMPORTANT** - For best ironing results on all table linen, feed tablecloths into the ironer leading with the Riegel label.